

Glastonbury Abbey – Soilmat & Geocoir



As part of the renovation of Glastonbury Abbey, the walls needed to be stabilised without destroying the existing character of the building. This included the grass surface which had grown on top of the walls since the Abbey's dissolution in 1539. The existing grassed area was cut back to enable work to take place on the walls. The surface of the rubble and soil filled walls was then covered with Soilmat or Geocoir depending on the construction of the specific wall. This was seeded and grass was allowed to reestablish.



Client  **DIOCESE OF
BATH & WELLS**